

EXHIBIT L

3-YEAR ASBESTOS INSPECTION REPORT

.....

JOHN G. WHITTIER ELEMENTARY SCHOOL SCRANTON, PA (NATIVITY - ANNEX BUILDING)

prepared for:

SCRANTON SCHOOL DISTRICT
425 North Washington Avenue
Scranton, Pa. 18505

CONSULTANTS:

Guzek Associates, Inc.
401 Davis Street
Clarks Summit, PA 18411

PROJECT: #SSD.19_751

Updated:

July 2019

TABLE OF CONTENTS

SECTION 1	EXECUTIVE SUMMARY
SECTION 2	INTRODUCTION
SECTION 3	BUILDING DISCRIPTION
SECTION 4	METHODS
SECTION 5	RE-INSPECTION FINDINGS
SECTION 6	RE-INSPECTION RESULTS
SECTION 7	RECOMMENDATIONS
SECTION 8	ASBESTOS INSPECTOR ACCREDIDATION
APPENDIX A	HOMOGENEOUS SAMPLING CHART, RESPONSE ACTION BASED ON HAZARD RANK, & ASBESTOS CONTAINING BUILDING MATERIAL (ACBM) LOCATION DRAWINGS
APPENDIX B	PLM SAMPLE ANALYSIS RESULTS & CHAIN-OF-CUSDOTY

ASBESTOS INSPECTION

For the property known as:

JOHN G. WHITTIER ELEMENTARY SCHOOL (ANNEX BUILDING)

SECTION 1 EXECUTIVE SUMMARY

An Asbestos Materials Inspection Survey was conducted on July 15, 2019 at the above-listed location. The purpose of the survey was to visually locate, identify, and assess asbestos-containing building materials. The survey was conducted by Certified Asbestos Inspectors, Chris Notari (DLI Asbestos Inspector Certification #027028)

All accessible rooms and areas of the building were entered for inspection of suspected asbestos materials. Suspected asbestos materials not previously sampled (if applicable) were sampled and sent to a laboratory for analyses to confirm or negate the suspicion of asbestos content. Other suspect materials were assumed to contain asbestos.

The results are summarized as follows:

A. Asbestos-containing Materials

1. All confirmed or assumed (roofing materials, chalkboard mastic, etc.) asbestos-containing materials are listed in Appendix A. Materials that were tested and found not to contain asbestos are also listed in Section 6.
2. Recommendations

Recommendations are given in relation to renovation maintenance and demolition activities for the school building in Section 7.

SECTION 2 INTRODUCTION

An Asbestos Materials Inspection of the John G. Whittier Elementary School (Annex Building) was performed at the request Scranton School District, Scranton, PA. The purpose of the inspection was to determine the types, quantities, and conditions of confirmed or assumed asbestos-containing materials, if not previously tested.

Once suspected asbestos materials were identified, they were sampled to verify or negate the suspicion of asbestos content (roofs were not tested and were assumed to contain asbestos). All materials sampled were analyzed via EPA Method 600/R-93/116 utilizing Polarized Light Microscopy by *EMSL Analytical, Inc., a NVLAP- accredited laboratory.*

The friability of these materials was also determined. Friable materials, such as cementitious pipe insulation, are those that can be crumbled, pulverized, or reduced to powder by hand or finger pressure. Non-friable materials, such as floor tiles in good condition, are those that cannot be crumbled, pulverized, or reduced to powder by hand or finger pressure. It is possible for normally non-friable materials to be considered as friable if they are in poor or damaged condition or will be rendered friable by construction or other activities, such as drilling, sanding, crushing by heavy equipment, etc.

The Initial Asbestos Hazard Emergency Response Act (AHERA) Building Inspection Report and Management Plan which was prepared and filed in accordance with the United States Environmental Protection Agency's (EPA) Regulation 40 CFR Part 763, Subpart E – Asbestos-Containing Materials in Schools is on file and available for review at the Scranton School District Administration Offices and John G. Whittier Elementary School (Annex Building) Administration Office.

SECTION 3 BUILDING DISCRIPTION

John G. Whittier Elementary School (Annex Building), located at 638 Hemlock Street, Scranton, PA is a wood and masonry building constructed approximately 1903. The building consists of a basement and three (3) floors, and contains approximately 40,000 square feet of floor area.

SECTION 4 METHODS

Prior to re-inspection the following documents were reviewed by Guzek Associates, Inc.

1. 2016 3-Year Re-inspection Report
2. AHERA 6-month Periodic Surveillance Inspection Reports

Upon completion of reviewing the above referenced documentation, Guzek Associates, Inc. conducted a room-by-room and area-by-area inspection of the building to verify the locations of Asbestos Containing Materials listed in the above documents and to determined the conditions (Good, Damaged, or Significantly Damaged) of these materials. In addition, suspect materials not listed in the above documents were identified and either assumed to contain asbestos or collected and analyzed to determined asbestos content.

The asbestos inspection survey was conducted by inspectors qualified by experience, education, and training in the recognition of suspected asbestos-containing materials. Sampling was limited to only areas that were easily accessible (above ceiling tiles, operable hatches, and open areas.) No walls, chases or ceilings, etc. were penetrated during this inspection.

For those materials analyzed for asbestos content during this inspection, representative samples of "suspected" asbestos-containing materials were collected utilizing approved federal and state methods.

All Samples collected were analyzed by EMSL Analytical, Inc., Cinnaminson, NJ. Using EPA 600/R-93/116 Method using Polarized Light Microscopy

SECTION 5 REINSPECTION FINDINGS

The attached inspection forms in Appendix A indicate both the locations and assessed conditions of confirmed or assumed asbestos containing materials as identified in the building by the 2019 Re-inspection conducted by Guzek Associates, Inc.

The Scranton School District intends to continue implementation of the Operations & Maintenance Program recommendations as contained in the AHERA Management Plan and to maintain its stringent occupational and environmental protection standards for the on-going control of the identified ACBM's within the building.

SECTION 6 INSPECTION RESULTS

A. Asbestos-containing Materials

Appendix A contains a list and drawings of all confirmed and assumed asbestos-containing materials identified in the Inspection report for John G. Whittier Elementary School (Annex Building) conducted by Guzek Associates, Inc.. This table also includes locations and condition assessments (Good, Damaged, or Significantly Damaged).

Finally all Chain of Custody and Analytical Laboratory Reports for the 2016 3-Year Re-inspection Report is included in Appendix B.

Note: In addition to those materials listed in the Homogeneous Sampling Chart in Appendix A, the following suspected asbestos-containing materials may be present:

1. Pipe and/or pipe fitting insulation (friable materials) in wall cavities in the vicinities of bathroom and shower fixtures, sinks, drinking water fountains, wall and ceiling chases – no access at time of inspection.
2. Glue pucks behind chalkboards (Category 1 non-friable material) – no access at time of inspection.
3. Fire Doors
4. Roofing Materials (including Flashing and Tar)
5. Electric wiring insulation maybe present

Materials That Were Tested and Found Not to Contain Asbestos

- All layers of hard wall and ceiling plasters
- Boiler Breeching
- Boiler Room Ceiling
- Brown thin linoleum like layer under carpet in classrooms
- Wall block
- Textured plaster (Kitchen Area)
- Gypsteel
- Ceiling block in attic
- Window sill tar paper
- 2'x2' & 2'x4' ceiling tile

SECTION 7 RECOMMENDATIONS

- A. Any Materials listed as Presumed Asbestos Containing Materials (PACM) in Appendix A shall either be assumed to contain asbestos or should be analyzed prior to disturbance to determine asbestos content at time of disturbance
- B. All Asbestos Containing Materials in the building that are to remain in place shall be treated according to Operation and Maintenance (O&M) procedures for each specific material and as listed in the O&M plan for the John G. Whittier Elementary School (Annex Building).
- C. All Presumed or Confirmed Asbestos Containing Materials that will be potentially damaged by any activity (renovation, demolition, maintenance, etc.) shall be:
 - 1. Removed by a Pennsylvania Department of Labor and Industry (PaDLI) Certified asbestos abatement contractor prior to renovation. Final clearance air monitoring should be performed by an independent third party contracted to the school district.

Or

- 2. The Activity that will potentially disturb Asbestos Containing Materials shall be designed to avoid said disturbance.

SECTION 8 ASBESTOS INSPECTOR ACCREDITATION

Certified PA Asbestos Inspectors, Chris Notari (DLI Asbestos Inspector Certification #027028). Copies of their certificates are included in this report on the following pages.

Certificate of Completion

awarded to

Chris Notari

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

7/11/19

Course Date

N/A

Exam Date

7/11/20


Expiration Date

Not Provided

Social Security Number

ACC-0719-6-005

Certificate Number


Mark K. Schlager
Training Director

APPENDIX A

REINSPECTION FINDINGS:

HOMOGENEOUS SAMPLING CHART

RESPONSE ACTION BASED ON HAZARD RANK

ASBESTOS CONTAINING BUILDING MATERIAL (ACBM) LOCATION DRAWINGS

Guzek Associates, Inc. - HOMOGENEOUS SAMPLING CHART

Scranton School District Building: John G. Whittier Elementary School (Annex Building) Dates of Original AHERA Inspection: July, 1988 Page 1 of 2

HOMOGENEOUS SAMPLING MATERIAL		MATERIAL CATEGORY	ASBESTOS CONTENT	FRIABILITY	AHERA ASSESSMENT	AHERA HAZARD	AHERA REMOVAL PRIORITY	NOTES
MATERIAL LOCATION	MATERIAL DESCRIPTION							
Basement, Boiler Room	Fittings /Pipe Insulation (Approx. 8 - 15 Fittings)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	N/A	N/A	N/A	Removed (12/2016) No Documentation was provided by District
Basement, Storage Room	Fittings /Pipe Insulation (Approx. 20 - 25 Fittings)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	N/A	N/A	N/A	Removed (12/2016) No Documentation was provided by District
1st Floor, Kitchen	Fittings /Pipe Insulation (Indeterminate)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	- Insulation is visible inside ceiling
1st Floor, Storage Under Steps	Black Tar Coating (Approx. 120 SQ FT)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	
2nd Floor, Nurse's Office	12"x12" Floor Tile & Mastic (Approx. 140 SQ FT)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	- Mastic Assumed
2nd Floor, Room 205 (Closet)	Fittings /Pipe Insulation (Approx. 8 LF of Insulation)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	
2nd Floor, Room 210 & Open Hole in closet ceiling	Fittings /Pipe Insulation (Approx. 10 LF of Insulation)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	6	2	
2nd Floor, Boy's Restroom	Fittings /Pipe Insulation (Approx. 2 - 5 Fittings) (Approx. 2 LF of Insulation)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	N/A	N/A	N/A	- Removed, No Documentation was provided by District. (Additional TSI may exists in this area)
2nd Room, Room 211	12"x12" Floor Tile & Mastic (Approx. 1,200 SQ FT)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	- Mastic Assumed
3rd Floor, Room 305 & Closet	Fittings /Pipe Insulation (Approx. 5 - 10 Fittings)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	N/A	N/A	N/A	- Removed, No Documentation was provided by District. (Additional TSI may exists in closet)
Throughout Building	Ductwork Flex Connections	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	- 3rd Floor, Girls restroom Janitor's Closet (Significantly Damaged, Remove)
	Mastic Behind Chalkboards, panels, and wallboards, etc.	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	- Not accessible during inspection

Information abstracted by: Christopher Notari in July, 2019

Friability: F = Friable, NF-1 = Non-Friable, NF-2 = Non-Friable
AHERA Assessment / Hazard Rank / Removal Priority = See Attached Document, "RESPONSE ACTIONS BASED ON HAZARD RANKING"

Building Inspector's Certification No.: 027028-PA

Assessment: G = Good, D = Damaged, SD = Significantly Damaged

Guzek Associates, Inc. - HOMOGENEOUS SAMPLING CHART

Scranton School District Building: John G. Whittier Elementary School (Annex Building) Dates of Original AHERA Inspection: July, 1988 Page 2 of 2


HOMOGENEOUS SAMPLING MATERIAL		MATERIAL CATEGORY	ASBESTOS CONTENT	FRIABILITY	AHERA ASSESSMENT	AHERA HAZARD	AHERA REMOVAL PRIORITY	NOTES
MATERIAL LOCATION	MATERIAL DESCRIPTION							
Throughout Building	Window Frame Caulking (Indeterminate)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	4	4	
	Window Glazing (Indeterminate)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	3	5	- Was reported by Lab as <1%. If disturbed more testing is required
	Textured Sink Coating on Exterior Base of Sinks	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	1	7	
	Mastic Behind Marble Walls (Indeterminate)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	1	7	
	Fittings /Pipe Insulation (Indeterminate)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	2	6	May exist behind, sink, water fountains, chases, ceilings, walls, and between floors
	Fire Doors (Indeterminate)	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	1	7	
	Boiler Room Fire Door	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	1	7	
	1st Floor, Stage Curtain	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	5	3	
	Gasketing Material	TSI SURFACE Misc.	Assumed or Analyzed	F NF-1 NF-2	G D SD	1	7	
Throughout Building, Mechanical Rooms								

Information abstracted by: Christopher Notari in July, 2019
 Friability: F = Friable, NF-1 = Non-Friable, NF-2 = Non-Friable
 AHERA Assessment / Hazard Rank / Removal Priority = See Attached Document, "RESPONSE ACTIONS BASED ON HAZARD RANKING"

Building Inspector's Certification No.: 027028-PA
 Assessment: G = Good, D = Damaged, SD = Significantly Damaged


RESPONSE ACTIONS BASED ON HAZARD RANK

HAZARD RANK	REMOVAL PRIORITY	AHERA CATEGORIES	RESPONSE ACTIONS REQUIRED BY AHERA
7	1	Significantly Damaged	Evacuate or restrict the area if needed. Remove the ACBM (or enclose or encapsulate it if sufficient to contain fibers). Repair of T.S.I. allowed if feasible and safe. O&M required for all ACBM.
6	2	Damaged with Potential for Significant Damaged	Evacuate or restrict the area if needed. Remove, enclose, encapsulate, or repair to correct damage. Take steps to reduce potential for disturbance. O&M required for all ACBM.
5	3	Damaged with Potential for Damage	Remove, enclose, encapsulate, or repair to correct damage. O&M required for all ACBM.
4	4	Damaged with Low Potential for Damage	Remove, enclose, encapsulate, or repair to correct damage. O&M required for all ACBM.
3	5	Good with Potential for Significant Damage	Evacuate or restrict the area if needed. Take steps to reduce potential for disturbance. O&M required for all ACBM.
2	6	Good with Potential For Damage	O&M required for all ACBM. Take steps to reduce potential for damage.
1	7	Good with Low Potential for Disturbance	O&M required for all ACBM



KEY - SURFACING ACM
NO SURFACING ACBM WAS
FOUND ON THIS LEVEL


BASEMENT PLAN
NOT TO SCALE



KEY - SURFACING ACM
ASSUMED ASBESTOS CONTAINING
SURFACING MATERIALS:
1. EXTERIOR COATING ON SINKS

1ST FLOOR PLAN
NOT TO SCALE

ACM LOCATIONS: 07-15-2019



Guzek Associates, Inc.
Mechanical, Electrical, Structural,
Environmental, and Architectural
Engineering
401 Davis Street
Clark Summit, PA 18411
Phone: (570) 586-9700
Fax: (570) 586-6728
E-Mail: guzekassoc@aol.com


DRAWN BY:	BM	CHECKED BY:	CN	JOB No.:	550 16_751	SCALE:	AS NOTED	DATE:	07/15/2019
DWG. TITLE:									2016 JOHN G. WHITTIER ELEMENTARY SCHOOL (Annex Building) FLOOR PLANS


ISSUED or REVISED	DATE

Scranton School District
Scranton School District
425 North Washington Avenue
Scranton, PA 18505

Asbestos Management Plans


DRAWING No.:


1



KEY - SURFACING ACM
ASSUMED ASBESTOS CONTAINING
SURFACING MATERIALS:
1. EXTERIOR COATING ON SINKS


2ND FLOOR PLAN
NOT TO SCALE



KEY - SURFACING ACM
ASSUMED ASBESTOS CONTAINING
SURFACING MATERIALS:
1. EXTERIOR COATING ON SINKS

3RD FLOOR PLAN
NOT TO SCALE

ACM LOCATIONS: 07-15-2019

**Guzek Associates, Inc.**
Mechanical, Electrical, Structural,
Environmental, and Architectural
Engineering
401 Davis Street
Clark, Summit, NJ 08411
Phone: (973) 586-9700
Fax: (973) 586-6728
E-Mail: guzekassoc@aol.com

DRAWN BY: BMT
CHECKED BY: CN
JOB No.: SSD 16_751
SCALE: AS NOTED
DATE: 07/15/2019

DWG. TITLE: 2016 JOHN G. WHITTER ELEMENTARY SCHOOL (Annex Building) FLOOR PLANS



ISSUED or REVISED	DATE

Scranton School District
Scranton School District
425 North Washington Avenue
Scranton, PA 18505



Asbestos Management Plans

DRAWING No.:
**A
2**

THERMAL ASBESTOS CONTAINING MATERIALS



BASEMENT PLAN
NOT TO SCALE



1ST FLOOR PLAN
NOT TO SCALE

NOTE: CEMENTITIOUS INSULATION AND FITTINGS MAY EXIST IN SEALED CEILING, WALLS, ETC.

Guzek Associates, Inc. Mechanical, Electrical, Structural, Environmental, and Architectural Engineering 401 Davis Street Clarif Summit, PA 18411 Phone: (570) 586-9700 Fax: (570) 586-6728 E-Mail: guzekassoc@aol.com	
DRAWN BY: BMT	CHECKED BY: CN
JOB No.: SSD 16-751	SCALE: AS NOTED
DATE: 07/15/2019	
DWC: TITLE: 2016 JOHN C. WHITTIER ELEMENTARY SCHOOL (Annex Building) FLOOR PLANS	

ISSUED or REVISED	DATE
REVISION	07/2019



Scranton School District
 Scranton School District
 425 North Washington Avenue
 Scranton, PA 18505

Asbestos Management Plans



DRAWING No.:
A3

ACM LOCATIONS: 07-15-2019

THERMAL ASBESTOS CONTAINING MATERIALS



2ND FLOOR PLAN
NOT TO SCALE



3RD FLOOR PLAN
NOT TO SCALE

NOTE: CEMENTITIOUS INSULATION AND FITTINGS MAY EXIST IN SEALED CEILING, WALLS, ETC.

ACM LOCATIONS: 07-15-2019

Guzek Associates, Inc.
Mechanical, Electrical, Structural, Environmental, and Architectural Engineering
401 Davis Street
Clark Summit, NJ 08411
Phone: (973) 586-9700
Fax: (973) 586-6728
E-Mail: guzek@guzek.com


DRAWN BY: BMT
CHECKED BY: CN
JOB No.: 550 16 751
SCALE: AS NOTED
DATE: 07/15/2019

DWG. TITLE: 2016 JOHN G. WHITTIER ELEMENTARY SCHOOL (Annex Building) FLOOR PLANS

Scranton School District
Scranton School District
425 North Washington Avenue
Scranton, PA 18505

Asbestos Management Plans

DRAWING No.:
A
4




KEY - MISCELLANEOUS ACM

ASSUMED ASBESTOS CONTAINING MISCELLANEOUS MATERIALS:

1. OLD ELECTRICAL WIRING

2. MARBLE MASTIC

BASEMENT PLAN
NOT TO SCALE



KEY - MISCELLANEOUS ACM

STAGE CURTAIN (ASSUMED)

CONFIRMED ASBESTOS CONTAINING MISCELLANEOUS MATERIALS:

1. INTERIOR WINDOW CAULKING

ASSUMED ASBESTOS CONTAINING MISCELLANEOUS MATERIALS:

1. CHALKBOARD MASTIC

2. MARBLE MASTIC

3. DUCTWORK FLEX CONNECTIONS

4. OLD ELECTRICAL WIRING

1ST FLOOR PLAN
NOT TO SCALE

ACM LOCATIONS: 07-15-2019

GA

Guzek Associates, Inc.

401 Davis Street
Clark Summit, PA 18411
Phone: (570) 586-9700
Fax: (570) 586-6728
E-Mail: guzek@ga-inc.com

DRAWN BY: BMT

CHECKED BY: CN

JOB No.: SSD 16_751

SCALE: AS NOTED

DATE: 07/15/2019

2016 JOHN G. WHITTIER ELEMENTARY SCHOOL (Annex Building) FLOOR PLANS

ISSUED or REVISED	DATE


Scranton School District

Scranton School District
425 North Washington Avenue
Scranton, PA 18505

Asbestos Management Plans

DRAWING No.: A5

Sheet Size: 36"x24"



KEY - MISCELLANEOUS ACM

12"x12" FLOOR TILE & MASTIC


CONFIRMED ASBESTOS CONTAINING MISCELLANEOUS MATERIALS:

1. INTERIOR WINDOW CAULKING

ASSUMED ASBESTOS CONTAINING MISCELLANEOUS MATERIALS:

1. CHALKBOARD MASTIC
2. MARBLE MASTIC
3. DUCTWORK FLEX CONNECTIONS
4. OLD ELECTRICAL WIRING

2ND FLOOR PLAN
NOT TO SCALE



KEY - MISCELLANEOUS ACM

CONFIRMED ASBESTOS CONTAINING MISCELLANEOUS MATERIALS:

1. INTERIOR WINDOW CAULKING

ASSUMED ASBESTOS CONTAINING MISCELLANEOUS MATERIALS:

1. CHALKBOARD MASTIC
2. MARBLE MASTIC
3. DUCTWORK FLEX CONNECTIONS
4. OLD ELECTRICAL WIRING

3RD FLOOR PLAN
NOT TO SCALE

ACM LOCATIONS: 07-15-2019

Scranton School District
425 North Washington Avenue
Scranton, PA 18505

Asbestos Management Plans

ISSUED or REVISED DATE

DRAWING No.: A6

Guze Associates, Inc.
Mechanical, Electrical, Structural, Environmental, and Architectural Engineering
401 Davis Street
Clark Summit, PA 18411
Phone: (717) 386-9700
Fax: (717) 386-6728
E-Mail: guzeassociates.com

DESIGNED BY: BMT
CHECKED BY: CN
JOB No.: SSD 16_751
SCALE: AS NOTED
DATE: 07/15/2019

DWG. TITLE: 2016 JOHN G. WHITTIER ELEMENTARY SCHOOL (Annex Building) FLOOR PLANS

APPENDIX B

TEST RESULTS FOR SUSPECTED ASBESTOS-CONTAINING MATERIALS:

2016 LABORATORY REPORT

2016 CHAIN OF CUSTODY

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnaslab@EMSL.com

EMSL Order: 041624880**Customer ID:** CLAG50**Customer PO:****Project ID:**

Attention: Chris Notari
 Guzek Associates, Inc.
 401 Davis Street
 Clarks Summit, PA 18411

Phone: (570) 586-9700
Fax: (570) 586-6728
Received Date: 09/06/2016 8:55 AM
Analysis Date: 09/10/2016 - 09/12/2016
Collected Date: 08/31/2016

Project: SSD 16_751 Nativity (Whittier Elem)

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized
 Light Microscopy**

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
01W 041624880-0001	1st floor, main lobby - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
02B 041624880-0002	1st floor, main lobby - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
03W 041624880-0003	1st floor, main lobby - Plaster white layer (1 layer)	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
04B 041624880-0004	1st floor, main lobby - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
05 041624880-0005	Basement-Coal storage room - Ceiling plaster (1 layer)	Gray Fibrous Homogeneous	5% Hair	95% Non-fibrous (Other)	None Detected
06 041624880-0006	Basement-Coal storage room - Floor material	Tan/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07 041624880-0007	Basement-Coal storage room - Floor debris	Gray Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
08 041624880-0008	Basement, boiler room-Boiler No. 1 - Boiler breeching (outer layer)	Beige Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected
09 041624880-0009	Basement, boiler room-Boiler No. 1 - Boiler breeching (inner layer)	Tan Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
10 041624880-0010	Basement, boiler room-Boiler No. 1 - Boiler breeching (outer layer)	Beige Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected
11 041624880-0011	Basement, boiler room-Boiler No. 1 - Boiler breeching (inner layer)	Tan Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
12 041624880-0012	Basement, boiler room-Boiler No. 2 - Boiler breeching (outer layer)	White Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected
13 041624880-0013	Basement, boiler room-Boiler No. 2 - Boiler breeching (inner layer)	Tan Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
14A 041624880-0014	Basement, boiler room-Boiler No. 2 - Boiler breeching (outer layer)	Beige Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected

Initial report from: 09/12/2016 15:36:04

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnaslab@EMSL.com

EMSL Order: 041624880

Customer ID: CLAG50

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
15B 041624880-0015	Basement, boiler room-Boiler No. 2 - Boiler breeching (inner layer)	Tan Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
16 041624880-0016	Basement, boiler room - Mastic on fiberglass ends <i>Result includes a small amount of inseparable attached material</i>	Brown/Yellow Fibrous Homogeneous	5% Glass	95% Non-fibrous (Other)	None Detected
17 041624880-0017	Basement, boiler room - Mastic on fiberglass ends <i>Result includes a small amount of inseparable attached material</i>	Brown/Yellow Fibrous Homogeneous	5% Glass	95% Non-fibrous (Other)	None Detected
18 041624880-0018	Basement, boiler room - Mastic on fiberglass ends <i>Result includes a small amount of inseparable attached material</i>	Brown/Yellow Fibrous Homogeneous	5% Glass	95% Non-fibrous (Other)	None Detected
19W 041624880-0019	Basement, boiler room (above steps) - Ceiling plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
20B 041624880-0020	Basement, boiler room (above steps) - Ceiling plaster base layer	Gray Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
21W 041624880-0021	Basement, boiler room (above incinerator) - Ceiling plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
22B 041624880-0022	Basement, boiler room (above incinerator) - Ceiling plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
23W-Plaster 041624880-0023	Gymnasium - Block wall white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
23W-Texture 041624880-0023A	Gymnasium - Block wall white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
24B 041624880-0024	Gymnasium - Block wall base layer	Tan Fibrous Homogeneous	60% Min. Wool	40% Non-fibrous (Other)	None Detected
25W-Plaster 041624880-0025	Gymnasium - Block wall white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
25W-Texture 041624880-0025A	Gymnasium - Block wall white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
26B 041624880-0026	Gymnasium - Block wall base layer	Tan Fibrous Homogeneous	60% Min. Wool	40% Non-fibrous (Other)	None Detected
27TP 041624880-0027	Kitchen - Textured plaster	White/Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
28W 041624880-0028	Kitchen - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 09/12/2016 15:36:04

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnasblab@EMSL.com

EMSL Order: 041624880

Customer ID: CLAG50

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
29B 041624880-0029	Kitchen - Plaster base layer	Gray Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
30TP 041624880-0030	Kitchen - Textured plaster	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
31W 041624880-0031	Kitchen - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
32B 041624880-0032	Kitchen - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
33TP 041624880-0033	Kitchen - Textured plaster	Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
34W 041624880-0034	Kitchen - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
35B 041624880-0035	Kitchen - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
36 041624880-0036	Ladies restroom off of gym, storage room - 2x2 ceiling tile	Gray/White Fibrous Homogeneous	50% Cellulose 30% Min. Wool	20% Non-fibrous (Other)	None Detected
37 041624880-0037	Ladies restroom off of gym - 2x4 ceiling tile	Gray/White Fibrous Homogeneous	60% Cellulose 30% Min. Wool	10% Non-fibrous (Other)	None Detected
38W 041624880-0038	Ladies restroom off of gym - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
39B 041624880-0039	Ladies restroom off of gym - Plaster base layer	Gray Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
40W 041624880-0040 limited sample	Staircase A, storage room - Wall plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
41B-Plaster 041624880-0041	Staircase A, storage room - Wall plaster base layer	Gray Fibrous Homogeneous	5% Hair	95% Non-fibrous (Other)	None Detected
41B-Plaster 2 041624880-0041A	Staircase A, storage room - Wall plaster base layer	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
42W 041624880-0042 limited sample	Staircase A, storage room - Wall plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
43B-Plaster 041624880-0043	Staircase A, storage room - Wall plaster base layer	Gray Fibrous Homogeneous	2% Cellulose 2% Hair	96% Non-fibrous (Other)	None Detected
43B-Plaster 2 041624880-0043A	Staircase A, storage room - Wall plaster base layer	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
44W 041624880-0044	Staircase A, storage room - Wall plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 09/12/2016 15:36:04

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnaslab@EMSL.com

EMSL Order: 041624880

Customer ID: CLAG50

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
45B-Plaster 041624880-0045	Staircase A, storage room - Wall plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
45B-Plaster 2 041624880-0045A	Staircase A, storage room - Wall plaster base layer	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
46 041624880-0046	2nd floor, hallway-Exterior of building - Exterior window caulking	Gray/White Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
47 041624880-0047	2nd floor, hallway-Exterior of building - Exterior window glazing	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
48 041624880-0048	2nd floor, office restroom - Exterior window caulking	Gray/White Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
49 041624880-0049	2nd floor, office restroom - Exterior window glazing	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
50W 041624880-0050	2nd floor, Room 206 - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
51B 041624880-0051	2nd floor, Room 206 - Plaster base layer	Gray Fibrous Homogeneous	2% Cellulose 2% Hair	96% Non-fibrous (Other)	None Detected
52-Brown Layer 041624880-0052	2nd floor, Room 208 - Brown layer under carpet	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
52-Mastic 041624880-0052A	2nd floor, Room 208 - Brown layer under carpet	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
53W 041624880-0053	2nd floor, Room 210 - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
54B 041624880-0054	2nd floor, Room 210 - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
55-Brown Layer 041624880-0055	2nd floor, Room 210 - Brown layer under carpet	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
55-Mastic 041624880-0055A	2nd floor, Room 210 - Brown layer under carpet	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
56 041624880-0056 <i>Result includes a small amount of inseparable attached material</i>	2nd floor, Room 210 - Mastic on fiberglass ends	Gray/White/Yellow Fibrous Heterogeneous	5% Glass	95% Non-fibrous (Other)	None Detected
57 041624880-0057	2nd floor, Room 210 closet - Gypsteel	Gray Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
58W 041624880-0058	2nd floor, boys' restroom - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
59B 041624880-0059	2nd floor, boys' restroom - Plaster base layer	Gray Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected

Initial report from: 09/12/2016 15:36:04

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnaslab@EMSL.com

EMSL Order: 041624880**Customer ID:** CLAG50**Customer PO:****Project ID:**

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
60W 041624880-0060	2nd floor, Room 207 - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
61B 041624880-0061	2nd floor, Room 207 - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
62 041624880-0062	3rd floor, hallway-Exterior of building - Exterior window caulking	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
63 041624880-0063	3rd floor, hallway-Exterior of building - Exterior window glazing	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
64 041624880-0064	3rd floor, Room 304 - Thin brown layer under carpet	Brown/Silver/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
65W 041624880-0065	3rd floor, Room 304 - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
66B 041624880-0066	3rd floor, Room 304 - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
67W 041624880-0067	3rd floor, janitor's closet - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
68B 041624880-0068	3rd floor, janitor's closet - Plaster base layer	Gray Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
69 041624880-0069	3rd floor, janitor's closet (behind plaster base layer) - Block	White Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
70 041624880-0070	3rd floor, Room 310 - Brown layer under carpet	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
71 041624880-0071	3rd floor, Room 311-Exterior of building - Exterior window caulking	White Non-Fibrous Homogeneous		96% Non-fibrous (Other)	4% Chrysotile
72 041624880-0072	3rd floor, Room 311-Exterior of building - Exterior window glazing	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
73W 041624880-0073	3rd floor, Room 309 - Plaster white layer	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
74B 041624880-0074	3rd floor, Room 309 - Plaster base layer	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
75 041624880-0075	Attic-Interior of building - Interior window sill paper (tar paper)	Black Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
76 041624880-0076	Attic-Interior of building - Interior window sill paper (tar paper)	Black Fibrous Homogeneous	70% Cellulose	30% Non-fibrous (Other)	None Detected

Initial report from: 09/12/2016 15:36:04

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3875 / (856) 786-5974

http://www.EMSL.com / cinnasblab@EMSL.com

EMSL Order: 041624880

Customer ID: CLAG50

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
77 041624880-0077	Attic-Interior of building - Ceiling block	Gray Fibrous Homogeneous	15% Cellulose	85% Non-fibrous (Other)	None Detected
78 041624880-0078	Attic-Interior of building - Ceiling block	White Fibrous Homogeneous	15% Cellulose	85% Non-fibrous (Other)	None Detected
79 041624880-0079	Attic-Interior of building - Ceiling block	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Analyst(s)

Andrew Castellano (4)

Quynh Vu (44)

Seri Smith (38)

Benjamin Ellis, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from: 09/12/2016 15:36:04



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Bulk Building Material

Chain of Custody

EMSL Order Number (Lab Use Only)

041624880

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077
PHONE: (800) 220-3675
FAX: (856) 786-5974

Company: Guzek Associates, Inc.		2015 SEP - 6 A 9:11	
Street: 401 Davis Street		EMSL-Bill to: <input type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
City: Clarks Summit	State/Province: PA	Zip/Postal Code: 18414	Country: U.S.A.
Report To (Name): Chris Notari		Telephone #: 570-586-9700	
Email Address: guzekassoc@aol.com		Fax #: 570-586-6728	Purchase Order:
Project Name/Number: SSD 16_751 Nativity (Whittier Elem.)		Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email	
U.S. State Samples Taken: Pennsylvania		CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt	
Turnaround Time (TAT) Options* - Please Check			
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input checked="" type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week			
*For TEM Air 3 hr through 6 hr, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide			
PLM - Bulk (reporting limit)		TEM - Bulk	
<input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)		<input type="checkbox"/> TEM EPA NOB - EPA 600/R-93/116 Section 2.5.5.1	
<input type="checkbox"/> PLM EPA NOB (<1%)		<input type="checkbox"/> NY ELAP Method 198.4 (TEM)	
Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)		<input type="checkbox"/> Chatfield Protocol (semi-quantitative)	
Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)		<input type="checkbox"/> TEM % by Mass - EPA 600/R-93/116 Section 2.5.5.2	
<input type="checkbox"/> NIOSH 9002 (<1%)		<input type="checkbox"/> TEM Qualitative via Filtration Prep Technique	
<input type="checkbox"/> NY ELAP Method 198.1 (friable in NY)		<input type="checkbox"/> TEM Qualitative via Drop Mount Prep Technique	
<input type="checkbox"/> NY ELAP Method 198.6 NOB (non-friable-NY)		Other	
<input type="checkbox"/> OSHA ID-191 Modified		<input type="checkbox"/>	
<input type="checkbox"/> Standard Addition Method			
<input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group		Date Sampled: 08-31-2016	
Samplers Name: Chris Notari / Brent Tripp		Samplers Signature: <i>Brent Tripp</i>	
Sample #	HA #	Sample Location	Material Description
01 W		1st Floor, Main Lobby	Plaster White Layer
02 B		1st Floor, Main Lobby	Plaster Base Layer
03 W		1st Floor, Main Lobby	Plaster White Layer (1 Layer)
04 B		1st Floor, Main Lobby	Plaster Base Layer
05		Basement - Coal Storage Room	Ceiling Plaster (1 Layer)
06		Basement - Coal Storage Room	Floor Material
07		Basement - Coal Storage Room	Floor Debris
08		Basement, Boiler Room - Boiler No. 1	Boiler Breeching (Outer Layer)
09		Basement, Boiler Room - Boiler No. 1	Boiler Breeching (Inner Layer)
10		Basement, Boiler Room - Boiler No. 1	Boiler Breeching (Outer Layer)
Client Sample # (s): 01 - 79		Total # of Samples: Seventy-Nine (79) <i>C/C</i>	
Relinquished (Client): <i>Brent Tripp</i>		Date: 09-01-2016	Time: 12:00 PM
Received (Lab): <i>Chelun EMILFX</i>		Date: 9/6/16	Time: 8:55
Comments/Special Instructions:			



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS-TRADESHOW

Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

071424880
2016 SEP -6 A 9:44

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077

PHONE: (800) 220-3675
FAX: (856) 786-5974

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	HA #	Sample Location	Material Description
11		Basement, Boiler Room - Boiler No. 1	Boiler Breeching (Inner Layer)
12		Basement, Boiler Room - Boiler No. 2	Boiler Breeching (Outer Layer)
13		Basement, Boiler Room - Boiler No. 2	Boiler Breeching (Inner Layer)
14 A		Basement, Boiler Room - Boiler No. 2	Boiler Breeching (Outer Layer)
15 B		Basement, Boiler Room - Boiler No. 2	Boiler Breeching (Inner Layer)
16		Basement, Boiler Room	Mastic On Fiberglass Ends
17		Basement, Boiler Room	Mastic On Fiberglass Ends
18		Basement, Boiler Room	Mastic On Fiberglass Ends
19 W		Basement, Boiler Room (Above Steps)	Ceiling Plaster White Layer
20 B		Basement, Boiler Room (Above Steps)	Ceiling Plaster Base Layer
21 W		Basement, Boiler Room (Above Incinerator)	Ceiling Plaster White Layer
22 B		Basement, Boiler Room (Above Incinerator)	Ceiling Plaster Base Layer
23 W		Gymnasium	Block Wall White Layer
24 B		Gymnasium	Block Wall Base Layer
25 W		Gymnasium	Block Wall White Layer
26 B		Gymnasium	Block Wall Base Layer
27 TP		Kitchen	Textured Plaster
28 W		Kitchen	Plaster White Layer
29 B		Kitchen	Plaster Base Layer
30 TP		Kitchen	Textured Plaster
31 W		Kitchen	Plaster White Layer
32 B		Kitchen	Plaster Base Layer
33 TP		Kitchen	Textured Plaster
34 W		Kitchen	Plaster White Layer
*Comments/Special Instructions:			



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS - TRAINING

Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only)

041624880

RECEIVED

EMSL

CINNAMINSON, N.J.

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077

PHONE: (800) 220-3675

FAX: (856) 786-5974

2016 SEP -6 A 9:11

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	HA #	Sample Location	Material Description
35 B		Kitchen	Plaster Base Layer
36		Ladies Rest Room Off Of Gym, Storage Room	2'x2' Ceiling Tile
37		Ladies Rest Room Off Of Gym	2'x4' Ceiling Tile
38 W		Ladies Rest Room Off Of Gym	Plaster White Layer
39 B		Ladies Rest Room Off Of Gym	Plaster Base Layer
40 W		Staircase A, Storage Room	Wall Plaster White Layer
41 B		Staircase A, Storage Room	Wall Plaster Base Layer
42 W		Staircase A, Storage Room	Wall Plaster White Layer
43 B		Staircase A, Storage Room	Wall Plaster Base Layer
44 W		Staircase A, Storage Room	Wall Plaster White Layer
45 B		Staircase A, Storage Room	Wall Plaster Base Layer
46		2nd Floor, Hallway - Exterior Of Building	Exterior Window Caulking
47		2nd Floor, Hallway - Exterior Of Building	Exterior Window Glazing
48		2nd Floor, Office Rest Room	Exterior Window Caulking
49		2nd Floor, Office Rest Room	Exterior Window Glazing
50 W		2nd Floor, Room 206	Plaster White Layer
51 B		2nd Floor, Room 206	Plaster Base Layer
52		2nd Floor, Room 208	Brown Layer Under Carpet
53 W		2nd Floor, Room 210	Plaster White Layer
54 B		2nd Floor, Room 210	Plaster Base Layer
55		2nd Floor, Room 210	Brown Layer Under Carpet
56		2nd Floor, Room 210	Mastic On Fiberglass Ends
57		2nd Floor, Room 210 Closet	Gypsteel
58 W		2nd Floor, Boy's Rest Room	Plaster White Layer
*Comments/Special Instructions:			



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS - TRAINING

Asbestos Bulk Building Material

Chain of Custody

EMSL Order Number (Lab Use Only) **041624880**
CINNAMINSON, N.J.

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077
PHONE: (800) 220-3675
FAX: (856) 786-5974

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	HA #	Sample Location	Material Description
59 B		2nd Floor, Boy's Rest Room	Plaster Base Layer
60 W		2nd Floor, Room 207	Plaster White Layer
61 B		2nd Floor, Room 207	Plaster Base Layer
62		3rd Floor, Hallway - Exterior Of Building	Exterior Window Caulking
63		3rd Floor, Hallway - Exterior Of Building	Exterior Window Glazing
64		3rd Floor, Room 304	Thin Brown Layer Under Carpet
65 W		3rd Floor, Room 304	Plaster White Layer
66 B		3rd Floor, Room 304	Plaster Base Layer
67 W		3rd Floor, Janitors Closet	Plaster White Layer
68 B		3rd Floor, Janitors Closet	Plaster Base Layer
69		3rd Floor, Janitors Closet (Behind Plaster Base Layer)	Block
70		3rd Floor, Room 310	Brown Layer Under Carpet
71		3rd Floor, Room 311 - Exterior Of Building	Exterior Window Caulking
72		3rd Floor, Room 311 - Exterior Of Building	Exterior Window Glazing
73 W		3rd Floor, Room 309	Plaster White Layer
74 B		3rd Floor, Room 309	Plaster Base Layer
75		Attic - Interior of Building	Interior Window Sill Paper (Tar Paper)
76		Attic - Interior of Building	Interior Window Sill Paper (Tar Paper)
77		Attic - Interior of Building	Ceiling Block
78		Attic - Interior of Building	Ceiling Block
79		Attic - Interior of Building	Ceiling Block
*Comments/Special Instructions:			